


Install weatronic-USB Drivers in Microsoft Windows 8

Microsoft Windows 8 enforces digital driver signature verification at the kernel level and would not allow users to install anything without it. Most of the time Windows 8 would show a error message like **"A digitally signed driver is required"** & **"The driver installation failed"**.


Thankfully, Microsoft has left an option to bypass the signature verification and install the device driver as usual. The procedure for installation of unsigned device drivers on Windows 8 is outlined below.

Procedure to enable installation of weatronic-USB Drivers in Microsoft Windows 8 :



1. To get started move your mouse-cursor to the **bottom right corner** of the screen and click **Settings** from the Charms bar






2. Now click **"Change PC Settings"**.



3. Navigate to **General** and then scroll to the bottom for **Advanced startup -> Restart now.**




4. Navigate to **Troubleshoot** -> **Advanced options** -> **Startup Settings** -> **Restart**



* lower right corner



5. Your computers will now restart and you have to chose "**Disable driver signature enforcement**". Use function key F7 to disable Windows 8 digital signature verification for driver installation for one single boot.



6. Now please install weatronic-USB Driver without getting blocked, keep in mind this setting is enabled for a single boot and will get disabled after next reboot.